

TERZANI
LA LUCE PENSATA

ART. 0M48P -- A
1xMAX 150W A21 E26

ART. 0M49P -- A
1xMAX 200W A23 E26




QC-PB-I

120V ~ 50Hz/60Hz


REPLACING THE FUSE

If the lamp does not light, check the fuse and if necessary proceed as explained below.
Check that the plug is disconnected from the line socket. Unscrew the screws (A) and open the dimmer box; check the state of the fuse (B) and if necessary replace with a new fuse with identical characteristics (F2, 5AH).


Type Y IEC attachment: any replacement can only be made by the manufacturer, his service agent or similar qualified person.



②



①



③

